

HID® FARGO® HDP® 6600

Windows Printer Driver
Release Notes

Driver Version: 1.0.1.52
PLT-04250, B.0
April 2025



Copyright

© 2019 - 2025 HID Global Corporation/ASSA ABLOY AB. All rights reserved.

This document may not be reproduced, disseminated, or republished in any form without the prior written permission of HID Global Corporation.

Trademarks

HID GLOBAL, HID, the HID Brick logo, HDP, and FARGO are trademarks or registered trademarks of HID Global, ASSA ABLOY AB, or its affiliate(s) in the US and other countries and may not be used without permission. All other trademarks, service marks, and product or service names are trademarks or registered trademarks of their respective owners.

MIFARE, MIFARE Classic, MIFARE DESFire, MIFARE DESFire EV1, MIFARE Plus, and MIFARE Ultralight are registered trademarks of NXP B.V. and are used under license.

Contacts

For technical support, please visit: <https://support.hidglobal.com>.

What's new

Date	Description	Revision
April 2025	Release notes for printer driver release 1.0.1.52.	B.0

A complete list of revisions is available in [Revision history](#).

1.1 Scope

This document provides information on HID® FARGO® HDP®6600 version 1.0.1.52. Included are product features, enhancements, and resolved issues since the previous release.

Note: The reference numbers associated with these features, issues, and fixes are from internal HID Global tracking systems.

Compatible operating systems:

- Windows 10 (32-bit and 64-bit)
- Windows 11 (64-bit)
- Windows Server 2016 (64-bit)
- Windows Server 2019 (64-bit)
- Windows Server 2022 (64-bit)

1.2 New features

- Added an indication of an encrypted job in the driver embedded PrnViewer. (FSA3-1277)

1.3 Resolved issues

- Resolved an issue with the driver **Defined Areas**. There was a failure to resize the area when manually entering height and width of less than 20mm. (FSA-1300, TTP-16686)
- Resolved an issue when upgrading a Chinese or Japanese language driver to v1.0.1.48, the driver interface language would not follow the Windows language. (FSA-1308, TTP-17138)
- Resolved an issue with the MIFARE DESFire card test. (FSA3-1443)
- Resolved an issue where the driver **Defined Areas** are not removed when **Restore driver defaults** was clicked. (FSA3-1495)
- Resolved an issue when restoring the defaults does not restore the **Defined Areas**. (XS-185)

1.4 Known issues

- The **System Event Log** error help file does not open after a reboot on Windows Server 2016 systems. (SICPI-527)
- Some errors which can be encountered (438, 441, 537, 534, 519, 509, 508, 470, and 469) do not display with a potential cause or resolution. (XL-746)
- When a ribbon is low, any errors which are encountered display both that error along with a ribbon low error. (XL-755)
- If a laminator is attached to a printer, closing the Printing Preferences always prompts the user to save the information even if none of the settings have been modified. (XL-768)
- The Alt-A hot key to invoke the Advanced tab does not work. (XL-778)
- Test Smart Card Encoding functionality is enabled at times when it should be disabled. (XS-505)
- When installing on a system configured for Japanese, Korean, or Simplified Chinese languages, some of the strings are either in English or are truncated. (XL-732)

Revision history

Date	Description	Revision
April 2025	Release notes for printer driver release 1.0.1.52.	B.0
August 2024	Release notes for printer driver release 1.0.1.48.	A.9
July 2024	Release notes for printer driver release 1.0.1.46.	A.8
January 2024	Release notes for printer driver release 1.0.1.44.	A.7
September 2023	Release notes for printer driver release 1.0.1.43.	A.6
March 2023	Release notes for printer driver release 1.0.1.42.	A.5
October 2022	Release notes for printer driver release 1.0.1.39.	A.4
February 2022	Release notes for printer driver release 1.0.1.33.	A.3
March 2020	Release notes for printer driver release 1.0.1.18.	A.2
August 2019	Release notes for printer driver release 1.0.1.12.	A.1
April 2019	Release notes for printer driver release 1.0.0.39.	A.0



hidglobal.com

For technical support, please visit: <https://support.hidglobal.com>

© 2025 HID Global Corporation/ASSA ABLOY AB.

All rights reserved.

PLT-04250, Rev. B.0

Part of ASSA ABLOY